



## Kenwood/iPod/XM Radio

- Kenwood MP3 Player (as illustrated in 2006 Accessory Guides)

- AM/FM/MP3/CD
- LCD display
- 220 watts
- OEM fit and finish
- Easy install kit (.5 hrs. recommended labor)



- iPod Adaptor Kit

- Plug and play with Kenwood MP3 Player
- Enjoy iPod programming through vehicle audio system
- Adapter plugs in rear of MP3 Player and routes behind dash to glovebox
- Concealed docking attachment in glove box for added security



- XM Radio

- Plug and play with Kenwood MP3 Player
- FREE activation
- FREE 3-month XM Radio subscription
- Enjoy XM entertainment through vehicle audio system
- Control XM programming through Kenwood MP3 Player
- XM module concealed behind radio with through glass antenna mount

- Available NOW for the following models:

- **Accent**                      **2006 – 2007**
- **Elantra**                     **2005 – 2007**
- **Tucson**                    **2004 – 2007**
- **Tiburon**                    **2005 – 2007**

**Note:** Kenwood MP3 Player is standard equipment on the 2006 and 2007 Tiburon SE. The iPod adaptor kit can be installed on this model and does not require replacement of the radio. The XM Module is not compatible with the 2006 or 2007 Tiburon SE.

| Description                                   | Model Applications | HMA Part Number | Dealer Net | Retail   |
|---|--------------------|-----------------|------------|----------|
| EZ500 Radio CD/MP3 AM/FM Radio                | All                | 00271-06000     | \$ 245.00  | \$400.00 |
| Radio Install Kit (Hardware + Wiring Harness) |                    |                 |            |          |
|   | Elantra            | 00271-86001     | \$ 19.50   | \$ 33.95 |
|   | Tucson             | 00271-T6000     | \$ 19.50   | \$ 33.95 |
|   | Tiburon            | 00271-E6002     | \$ 19.50   | \$ 33.95 |
|   | Accent             | 00271-Q6001     | \$ 19.50   | \$ 33.95 |
| XM Kit (Receiver, Interface Box, Antenna)     |                    |                 |            |          |
|   | All                | 00271-06003     | \$ 132.00  | \$231.00 |
| iPod Audio Adapter                            |                    |                 |            |          |
|   | All                | 00271-06001     | \$ 75.00   | \$129.00 |

\*Kenwood MP3 play DOES NOT qualify for HMA radio upgrade program credit

# KENWOOD AND XM TROUBLESHOOTING GUIDE

For all typical radio malfunctions to include power failure, tuning problems, sound, etc. please follow normal audio replacement procedures.

When there is a problem specifically with the XM receiver, the Kenwood head unit will display the following error messages respective to the problem being encountered.

## **ERROR MESSAGE:**

### **ANTENNA**

The antenna is not connected properly.

- Check the connection of the antenna to the XM tuner box.

### **UPDATING**

Radio is being updated with latest encryption code.

- Wait until the encryption code updates. Channels 0 and 1 should function normally.
- You have not subscribed to XM service.
- Contact XM to subscribe.

### **NO SIGNAL**

XM signal is being blocked from reaching the XM antenna.

- The message should disappear as soon as you move out of an obstructed area such as an indoor garage. If the problem persists, make sure your antenna is mounted outside and on top of the car with a clear view of the sky.

### **OFF AIR**

The channel currently selected has stopped broadcasting.

- Automatically switches to valid channel. No action is required.

### **LOADING**

The receiver is reading the channel information.

- Wait until the XM tuner completes receiving the information.

### **NO INFO**

No information is available to display.

- No action is required.

### **“CH ---“**

The channel to be tuned is void due to a channel lineup change.

The tuner will automatically switch to a valid channel.

- No action is required.

## **Replacing the XM unit:**

1. Verify the receiver is faulty.
2. Replace the XM receiver.
3. Call XM Listener Care at 800-852-9696
4. Identify themselves as a dealer replacing a defective radio for a customer.
5. Provide the old XM ID, the new XM ID, and customer information (Name, address, etc.)  
( XM ID is located on the tuner box, or on channel 0 when the box is connected to the headunit.)
6. The new radio will be activated on the users account.
7. Follow normal activation instructions to get the radio to activate.